

# BioWorld Products

California • USA • Worldwide

## Amusement Park Algae Treatment Case Study



A west coast amusement park had a 2 acre pond that was nearly covered with algae. Chemical treatments were done in the past but the algae continued to be a problem for the park staff and visitors.



BioWorld Algae Treatment products were applied each week. After 6 weeks, the algae were completely eliminated. Annual maintenance treatments have continued to balance the ecosystem for the long term with environmentally safe and natural products.



**BioWorld Products used:**  
**35064 Liquid Optimizer**  
**30086 Algae Competitor Microbes**