

Advanced BioTech

Developer of BioWorld Products

Algae Treatment in Condominium Complex Pond



A condominium complex had a pond that was covered with algae. Copper sulfate products were used in the past, but did not fix the problem.



BioWorld Algae Treatment products were applied each week. After 4 weeks, the algae dissipated and the pond was beautiful for the residents and guests.

BioWorld Products used:

35014 Liquid Optimizer

30086 Algae Competitor Microbes