

# BioWorld Products

California • USA • Worldwide

## In-Situ Bioremediation of Gasoline Contaminated Groundwater Case Study



Underground storage tanks were removed from an old service station in the mid 1990's. Gasoline had leaked out of the tanks and contaminated the shallow groundwater. An engineering firm was hired to begin the cleanup and 6 monitoring wells were installed. After 7 years of monitoring, there were no changes in the analytical tests and the firm was released. BioWorld teamed up with a progressive and innovative engineering firm determined to clean up the groundwater.

BioWorld designed a specialized pump and treat system and procedure using the existing monitoring wells. The site work and cleanup had to be performed with the existing auto sales business operating on the property.



BioWorld Bioremediation Enhancer and Hydrocarbon Digesting Microbes were added several times down the monitoring wells. Within 5 days, 8 inches of free floating product had been degraded. Treatment continued for 3 months with a 90% reduction in dissolved phase gasoline constituents verified.

**BioWorld Products used:**  
**75064 Bioremediation Enhancer**  
**32086 Hydrocarbon Digester Microbes**

---

[www.bioworldusa.com](http://www.bioworldusa.com) • [mail@bioworldusa.com](mailto:mail@bioworldusa.com) • 559.651.2042

International Headquarters • R&D • Manufacturing • Distribution Center

8244 W Hillsdale Ct • PO Box 2920 • Visalia California 93279-2920 • United States of America

Copyright © 1991-2006. All rights reserved