

BioWorld Products

California • USA • Worldwide

Oil Sludge Bioremediation Case Study Bench Scale Test



Oil Sludge from old well drilling pit. Side by side comparison. (See dried lump in tanks.)
Left – Control
Right – Treated with BioWorld Hydrocarbon Treatment Products.



Several days later.
Left (Control) – Water has no signs of biological activity.
Right (Treated) – Respiration from microbes degrading the hydrocarbon very apparent.



Several days later.
Left (Control) – Water has no signs of biological activity.
Right (Treated) – Respiration from microbes degrading the hydrocarbon very apparent.

Fatty Acids forming on surface as hydrocarbon breaks down.

BioWorld Products used:
75014 Bioremediation Enhancer
32086 Hydrocarbon Digester Microbes

www.bioworldusa.com • mail@bioworldusa.com • 559.651.2042

International Headquarters • R&D • Manufacturing • Distribution Center

8244 W Hillsdale Ct • PO Box 2920 • Visalia California 93279-2920 • United States of America

Copyright © 1991-2006. All rights reserved