

BioWorld Products

California • USA • Worldwide

ASPHALT ODOR CASE STUDY

Project Situation

Asphalt odors from a roofing project caused company office personnel to complain of headaches and stomach aches. This reduced the productivity of the staff and business. BioWorld was contacted to provide an odor control solution.

Products/Technology Used

#41064 BioWorld Odor Neutralizer BON-CC-41 Concentrate
#F8026 Triple Nozzle Fogger

Results

BON CC-41 was diluted and fogged directly into the heating, ventilation and air conditioning (HVAC) intake. The odor neutralizer was dispersed throughout the office building. The asphalt odor was eliminated within an hour and the staff returned to work. Maintenance workers continued to fog the BON CC-41 into the ductwork until the roofing process was completed.